


# AcuMesh Wiring Example: 1 Master and 1 Slave



## RS485 - Default Configuration

Baud Rate: 9600

Data Bits: 8

Stop Bits: 1

Parity: N